

**Save 800 mil dollars  
we explain**



**SE//EQ**

# COST AVOIDANCE

---

We prevented about 20 hours of downtime, saving around **\$800,000!**



**0.8M USD**  
SAVINGS


**SE//EQ**

# ONLINE SYSTEM

We installed Axon HD vibration wireless sensors and the Elektron MCA 460V sensor to monitor the mechanical and electrical conditions of the electric motor and gearbox.




**SEMEQ**



# ELECTRICAL ISSUES


The vibration system identified an electrical frequency of 120 Hz—twice line frequency—suggesting an electrical issue. We observed an amplitude of around 2.5g in the envelope for the main motor. Let's explore this further together!



# ELEKTRON MCA

We checked over the Elektron MCA for a deeper insight into electrical frequency! We've identified the Short Circuit Frequency (SCF) and the Broken Bar Frequency (BBF), enhancing our understanding.

	A	B	C
Test Date	04/06/18	02/14/19	09/18/24
Test Time	6:18 AM	12:25 PM	2:10 PM
Test Location	Motor Leads	Motor Leads	Junction Box
User	Administrator	Administrator	Administrator
Tester Serial	5904	5904	5904
MTAP ID			
	Baseline		
Frequency	1200	1200	1200
Charge Time	600	600	600
Voltage	500	500	500
Motor Temp °F	104	59	90
Measured Mohm	3,830.82	3,704.53	144.14
Corrected Mohm	3,830.82	650.00	83.90
pF Ph 1 to Ground	128.200	131.800	94.500
ohm Ph 1 to 2	0.00334	0.00336	0.00358
ohm Ph 2 to 3	0.00337	0.00344	0.00360
ohm Ph 3 to 1	0.00327	0.00328	0.00330
mH Ph 1 to 2	1.060	1.050	0.900
mH Ph 2 to 3	0.980	0.995	0.895
mH Ph 3 to 1	1.035	0.960	0.880
Average Inductance	1.025	1.000	0.890
% Res. Imbalance	1.70	2.34	0.39
% Ind. Imbalance	4.39	4.83	4.67



# MCA TEST RESULTS

We conducted the complimentary MCA test and found some interesting insights! It revealed that the Main Motor Saw 1 has poor isolation and there is notable rotor eccentricity in Main Motor Saw 2. Exciting opportunities for improvement!



# ACTION REQUIRED

We have two important reports! Monitor the online data for the Main Motor Saw 2 and prioritize rebuilding the Main Motor Saw 1. These actions had a significant impact!

# ASSESS DAMAGE PARTS

After maintenance, the assessment of the motor revealed cracks in the rotor bars, excessive dust, and the presence of water in the stator, which were diagnosed using the sensors.




Rotor crack



Excessive dust



Water presence



# GEARBOX ISSUES

We observed some rotational looseness in the input bearing. After monitoring the data closely, we recommended a gearbox overhaul once the amplitude levels rose, ensuring optimal performance!

# ASSESS GEARBOX

It was discovered during the assessment that there was excessive clearance between the shaft and the housing.





**FOLLOW  
FOR MORE  
GREAT CASES  
LIKE THAT!**

**SE//EQ**